




ASSEMBLY PROCESS FLOW CHART



Legend: SMT - Surface Mount; T/H - Through Hole; T/U - Touch-Up